

February 2022 Incident Report

02/22/2022 9:40 PM The waterfront gate had been damaged or altered so it could not be locked. The U-style clamps that hold the pivot point on the gate were spun as to not allow the gate to come together for locking purposes. Also, the large sign that tells everyone that vehicles can be impounded after dark was lying flat on the ground like someone had cut the ties that secure it to the fencing. Gate was promptly repaired in short order by Don the next morning.